

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 39

Dated: 10/04/2026

It is certified that the existing building ST JOSEPHS SCHOOL, (name of the building or premises) at ISLAMPUR, NALNDA, BIHAR, 801303.

..... (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	03 G+2	NA	NA	NA	NA	NA

The building is owned/occupied by ST JOSEPHS SCHOOL, ISLAMPUR, NALNADA, BIHAR. (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of BUILDING CONST. DEPT. (Name of Department/ Govt.) on 10/04/2026 (date of inspection) in the presence of RENNY JOHN, Principal, St. JOSEPHS, Islampur (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 10/04/2026 for a period of 1 (ONE) years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 10/04/2026 at HILSA by Building Sub-division, Nalanda

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : Ashutosh Kumar

Designation : Assistant Engineer

Name & Address of Department/ Office: B.C.D, Nalanda

सहायक अभियंता  
भवन अवर प्रमंडल  
हिलसा (नालन्दा)